Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	71602	pressure adj (sensor or detector or transducer or gage or gauge)	USPAT	OR	OFF .	2005/07/08 12:55
L2	244	clamp\$ near3 cuff	USPAT	OR	OFF	2005/07/08 12:53
L3	2406748	fasten\$ or connect\$	USPAT	OR	OFF	2005/07/08 12:54
L4	114935	(fasten\$ or connect\$) near2 (sensor or gage or gauge or detector or transducer)	USPAT	OR	OFF	2005/07/08 12:54
L5	14362	strain adj (sensor or detector or transducer or gage or gauge)	USPAT	OR	OFF	2005/07/08 12:55
L6	2	1 and 2 and 3 and 4 and 5	USPAT	OR	OFF	2005/07/08 12:55

